

Management Station Coexistence: Command View for Tape Libraries and Command View EVA software



397027-001

Part number: 397027-001
First edition: May 2005

Management Station Coexistence: Command View for Tape Libraries and Command View EVA software

Recent testing has confirmed that the following versions of Command View can be installed on the same Windows management station:

- Command View for Tape Libraries, version 1.5.05 and later
- Command View EVA, version 3.3.3 and later

The management station must meet the following minimum criteria:

- Windows 2000 or 2003 Professional or Server edition SP3, or Windows XP Professional
- Pentium IV 1.6 GHz processor, 2 GB RAM
- Java JRE 1.4.2

Please note that only a single SMI-S Provider (or “CIMOM”) can be installed on a management station at this time. When Command View for Tape Libraries and Command View EVA are installed on the same management station, either the Tape Library Provider or EVA Provider – but not both – can be installed. *

Additional documentation on HP StorageWorks Command View for Tape Libraries, HP StorageWorks Command View EVA, and SMI-S is available at at: <http://www.hp.com>.

* Installing the Tape Library provider after installing the EVA provider can cause the CIMOM to fail startup, while installing the EVA provider after installing the Tape Library provide can cause provider functional calls to fail. Uninstalling both providers and reinstalling only one results in normal operation.

© Copyright 2005 Hewlett-Packard Development Company, L.P.

Hewlett-Packard Company makes no warranty of any kind with regard to this material, including, but not limited to, the implied warranties of merchantability and fitness for a particular purpose. Hewlett-Packard shall not be liable for errors contained herein or for incidental or consequential damages in connection with the furnishing, performance, or use of this material.

This document contains proprietary information, which is protected by copyright. No part of this document may be photocopied, reproduced, or translated into another language without the prior written consent of Hewlett-Packard. The information is provided "as is" without warranty of any kind and is subject to change without notice. The only warranties for HP products and services are set forth in the express warranty statements accompanying such products and services. Nothing herein should be construed as constituting an additional warranty. HP shall not be liable for technical or editorial errors or omissions contained herein.

Microsoft®, Windows®, Windows NT®, and Windows® XP are U.S. registered trademarks of Microsoft Corporation.

UNIX® is a registered trademark of The Open Group.

Java™ is a US trademark of Sun Microsystems, Inc.